

Feeding Screw

CAD RoHS

Accessories

X

XY

Z

Horizontal
Z

XZ

Horizontal
XZ

XYZ

Horizontal
XYZ


Goniometer

Rotary

Unit


Accessories

Feeding screw
B85-1




Stroke (mm)	±6.5
Screw pitch (mm/1 rotation)	0.5
Weight (kg)	0.03

Feeding screw
B85-2




Stroke (mm)	±3.2
Screw pitch (mm/1 rotation)	0.5
Weight (kg)	0.005

Feeding screw
B85-3




Stroke (mm)	±12.5
Screw pitch (mm/1 rotation)	0.5
Weight (kg)	0.05

Feeding screw (Fine pitch)
B86-1




Stroke (mm)	±6.5
Screw pitch (mm/1 rotation)	0.25
Weight (kg)	0.03

Feeding screw (Fine pitch)
B86-2




Stroke (mm)	±3.2
Screw pitch (mm/1 rotation)	0.25
Weight (kg)	0.005

Feeding screw (Long pitch)
B87-1




Stroke (mm)	±6.5
Screw pitch (mm/1 rotation)	1.0
Weight (kg)	0.03

Feeding screw (Long pitch)
B87-3




Stroke (mm)	±12.5
Screw pitch (mm/1 rotation)	1.0
Weight (kg)	0.05

Feeding screw (Handled by hex wrench)
B88-1




Stroke (mm)	±6.5
Screw pitch (mm/1 rotation)	0.5
Weight (kg)	0.015

Feeding screw
(Handled by hex wrench)
B88-2




Stroke (mm)	±3.2
Screw pitch (mm/1 rotation)	0.5
Weight (kg)	0.005

Feeding screw
(Fine pitch: Handled by hex wrench)
B89-1



Stroke (mm)	±6.5
Screw pitch (mm/1 rotation)	0.25
Weight (kg)	0.015

Feeding screw
(Fine pitch: Handled by hex wrench)
B89-2



Stroke (mm)	±3.2
Screw pitch (mm/1 rotation)	0.25
Weight (kg)	0.005